Dart Aerospace Ltd. Wednesday, 6/20/2007 11:21:32 AM Date: Kim Johnston User **Process Sheet** : FWD X-TUBE **Drawing Name** Customer : CU-DAR001 Dart Helicopters Services Job Number : 33025 Estimate Number : 10006 : D2889 : NA Part Number P.O. Number : D2889 REV B S.O. No. : NIA **Drawing Number** This Issue : 6/20/2007 : N/A : NC Project Number Prsht Rev. NA : LANDING GEAR **Drawing Revision** : B First Issue : 33024 Al4: Material Previous Run : 6/27/2007 Each Qty: 1 Um: **Due Date** Written By Checked & Approved By... Est Revt A درية 05-10-25 JLM Comment New Issue **Additional Product** Job Number: Machine Or Operation: Description: Seq. #: D6005180 Crosstube material 1.0 Comment: Qty.: 1.0000 Each(s) 1.0000 Each(s)/Unit Total: Crosstube material Pick: Qty Part number Description Fwd Crosstube 1 D2889 BENDING 2.0 Comment: LANDING GEAR RESOURCE 1 1-Bend D2889 as per Dwg D2889 and Folio FT001 7-6-26 LANDING GEAR RESOURCE 1 3.0 LANDING GEAR 1 Comment: LANDING GEAR RESOURCE 1 1-Deburr and Polish DIMENSIONAL CHECK QC6 4.0 Comment: DIMENSIONAL CHECK HAND FINISHING RESOURCE #1 5.0 HAND FINISHING1

Comment: HAND FINISHING RESOURCE #1

Acid etch and alodine as per QSI 005 4.1

Inside and outside of tube

## **Dart Aerospace Ltd**

W/O:		WORK ORDER CHANGES	3	· · · · · · · · · · · · · · · · · · ·			
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	<del></del>		<u>L</u>				<u> </u>

Part No:	PAR #:	Fault Category:	-	NCR: Yes No	DQA:	Date: <u>09/04/04</u>
				QA: N/C C	losed:	Date:

NCR:			WORK ORDI	ER NON-CONFORMANO	CE (NCR)			
		Description of NC	Corrective Action Section B		Verification Approval	Approval		
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector
					İ			

NOTE: Date & initial all entries



Date: User:

Wednesday, 6/20/2007 11:21:32 AM

Kim Johnston

**Process Sheet** 

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: FWD X-TUBE

Job Number: 33025

Part Number: D2889

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

6.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION

WA.

Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

7.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location: UN 32939

8.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



## **Dart Aerospace Ltd**


W/O:		WORK ORDER CI	ANGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspector
	·						
		.•					
Part No		PAR #: Fault Category:	NCR: Yes	No DQ	A:	Date:	
			QA:	N/C Close	d:	Date:	

NCR:	R: WORK ORDER NON-CONFORMANCE (NCR)							
		Description of NC	Corrective Action Section B			Verification Appro	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C		Approval QC Inspector
						,		
				<u>-</u>				
								,

NOTE: Date & initial all entries

DART AEROSPACE LTD		Work Order:	33025
Description: Crosstube Fwd		Part Number:	D2889
Inspection Dwg: D2889	Rev: B		Page 1 of 1

Required Dimension	Min	Max
Height	49.875	50.125
1/2 Span	69.275	69.525
Angle	49	52
Total Span	138.55	139.05



	Comments
Tube is to be cu-	Jer - 101 B32939
	1
QC15 Inspection	
Date	407040

Rev	Date	Change	Revised by	Apprøved
Α	07.02.06	New Issue	KJ/JM KJ/	m
L	<u> </u>		. ()	

